



Broady Steelhead Barrier Removal 2020



Legend

- Arches to Remove
- Shallow Culverts between Arches
- Deeper Culverts under Debris Flows
- Slump Narrows Road
- Trash Rack
- Roads Decommissioned in 2019
- W side - 505 Rd: FSV/OHV Access
- E side - 505 Rd: Storage
- Section
- FS boundary



Broady Fish Distribution and Streamflow, 2020

