



*Figure 3-3. Photo of an avulsion blocked by a jam at RM 5.3. Note the gravel material deposited upstream.*



*Figure 3-4. Photo of an avulsion channel that has cut through the densely forested floodplain at RM 5.2. Note the low width-to-depth ratio, the large wood, and the bank vegetation.*